

SL	Description of Item (LOT 5 Toyota Prado/Fortuner)	Unit	CHHEME AUTO
1	Timing Belt with Labour/Service Charge	Nos	5500
2	Timing Belt Kit with Labour/Service Charge	set	200
3	V-Belt with Labour/Service Charge	Nos	500
4	Front Brake Pads (a pair) with Labour/Service Charge	set	12000
5	Rear Brake Pads (a pair) with Labour/Service Charge	set	12000
6	Brake Repair Kit (set of 2) with Labour/Service Charge	set	300
7	Brake Fluid with Labour/Service Charge	L	600
8	Break Shoes (set of 2) with Labour/Service Charge	set	7800
9	Drum Brake with Labour/Service Charge	Nos	8500
10	Front Brake Disc with Labour/Service Charge	Nos	8500
11	Rear Brake Disc with Labour/Service Charge	Nos	100
12	Anti-Lock Braking System (set of 2) with Labour/Service Charge	set	500
13	Brake Booster with Labour/Service Charge	Nos	18000
14	Brake Cable with Labour/Service Charge	Nos	100
15	Brake Caliper (1 pair) with Labour/Service Charge	set	12000
16	Brake Disc (set of 2) with Labour/Service Charge	set	0
17	Brake Disc Bolt with Labour/Service Charge	Nos	350
18	Brake Fluid Reservoir with Labour/Service Charge	Nos	0
19	Brake Hose with Labour/Service Charge	Nos	800
20	Brake Hose Connector with Labour/Service Charge	Nos	600
21	Brake Light Switch with Labour/Service Charge	Nos	2800
22	Brake Master Cylender with Labour/Service Charge	set	9800
23	Brake Master Cylinder Repair Kit with Labour/Service Charge	set	100
24	Brake Pads with Labour/Service Charge	set	0
25	Brake Pad Wear Sensor with Labour/Service Charge	Nos	500
26	Brake Pedal with Labour/Service Charge	Nos	500
27	Brake pipe with Labour/Service Charge	Nos	500
28	Brake Power Regulator with Labour/Service Charge	Nos	500
29	Brake Proportioning Valve with Labour/Service Charge	Nos	300
30	Brake Shoe Lining with Labour/Service Charge	Nos	0
31	Brake System Bracket with Labour/Service Charge	Nos	300
32	Caliper Bracket with Labour/Service Charge	Nos	300
33	Drum Brake with Labour/Service Charge	Nos	0
34	Drum Brake Adjuster with Labour/Service Charge	Nos	1200
35	Hand break Repair Kit with Labour/Service Charge	Nos	200
36	Hand Break Warning Light Switch with Labour/Service Charge	Nos	200

SL	Description of Item (LOT 5 Toyota Prado/Fortuner)	Unit	CHHEME AUTO
37	Vacuum Hose with Labour/Service Charge	Nos	300
38	Vacuum Pump with Labour/Service Charge	Nos	300
39	Wheel Break Cylinder and Kit with Labour/Service Charge	set	700
40	Clutch (clutch plate, Pressure plate and release bearing with Labour/Service Charge	set	55000
41	Clutch Kit with Labour/Service Charge	set	100
42	Clutch Cable with Labour/Service Charge	Nos	100
43	Clutch Hose with Labour/Service Charge	Nos	200
44	Clutch Master Cylender with Labour/Service Charge	Nos	6800
45	Clutch Release Fork with Labour/Service Charge	Nos	3800
46	Clutch Release Lever with Labour/Service Charge	Nos	500
47	Clutch Release Shaft with Labour/Service Charge	Nos	300
48	Clutch Slave Cylinder with Labour/Service Charge	Nos	200
49	Flywheel Ring with Labour/Service Charge	Nos	1500
50	Air Filter with Labour/Service Charge	Nos	3200
51	Cabin Filter with Labour/Service Charge	Nos	400
52	Fuel Filter with Labour/Service Charge	Nos	1500
53	Oil FIlter with Labour/Service Charge	Nos	980
54	Horn with Labour/Service Charge	Nos	700
55	Break Light Switch with Labour/Service Charge	Nos	0
56	Bulb Socket with Labour/Service Charge	set	400
57	Fog Lamp with Labour/Service Charge	set	1500
58	Fog Lamp Bulb with Labour/Service Charge	Nos	400
59	Fog Lamp Switch with Labour/Service Charge	Nos	500
60	Hazard Light Switch with Labour/Service Charge	Nos	300
61	Headlight with Labour/Service Charge	Nos	16500
62	Headlight Bulb with Labour/Service Charge	Nos	300
63	Indictor with Labour/Service Charge	set	100
64	Indicator Bulb with Labour/Service Charge	Nos	100
65	Number Plate Light with Labour/Service Charge	Nos	600
66	Number Plate Light Bulb with Labour/Service Charge	Nos	500
67	Passenger Compartment Light with Labour/Service Charge	Nos	20
68	Reverse Light Switch with Labour/Service Charge	Nos	50
69	Stop Light Bulb with Labour/Service Charge	Nos	100
70	Tail Light with Labour/Service Charge	Nos	300
71	Front Shock Absorber with Labour/Service Charge	Nos	8800
72	Rear Shock Absorber with Labour/Service Charge	Nos	8000

SL	Description of Item (LOT 5 Toyota Prado/Fortuner)	Unit	CHHEME AUTO
73	AC Compressor with Labour/Service Charge	Nos	500
74	AC Composer Clutch with Labour/Service Charge	Nos	300
75	AC Compressor Oil with Labour/Service Charge	L	300
76	AC Compressor Valve with Labour/Service Charge	Nos	200
77	AC Control Unit with Labour/Service Charge	set	300
78	AC Pressure Switch with Labour/Service Charge	Nos	300
79	Air Duct with Labour/Service Charge	Nos	200
80	Alternator Pulley with Labour/Service Charge	set	300
81	Belt Pulley with Labour/Service Charge	set	300
82	Crankshaft Pulley with Labour/Service Charge	set	300
83	Deflection Pulley with Labour/Service Charge	Nos	300
84	Timing Belt with Labour/Service Charge	Nos	0
85	Timing Belt Kit with Labour/Service Charge	set	0
86	Timing Chain with Labour/Service Charge	Nos	2200
87	Timing Chain Guide with Labour/Service Charge	Nos	1800
88	V-belt with Labour/Service Charge	Nos	0
89	Rear Wheel Bearing with Labour/Service Charge	set	800
90	Pilot Bearing with Labour/Service Charge	Nos	980
91	Shock Absorber Bearing with Labour/Service Charge	Nos	50
92	Transmission Bearing with Labour/Service Charge	Nos	300
93	Alternator Bearing with Labour/Service Charge	Nos	800
94	Big End Bearing with Labour/Service Charge	Nos	50
95	Crankshaft Bearing with Labour/Service Charge	Nos	980
96	Front Wheel Bearing with Labour/Service Charge	Nos	800
97	Automotive Tape with Labour/Service Charge	Nos	200
98	Beam Axle with Labour/Service Charge	Nos	1200
99	Body Rubber Stop with Labour/Service Charge	set	500
100	Bonnet with Labour/Service Charge	Nos	9000
101	Boot with Labour/Service Charge	Nos	0
102	Bumper with Labour/Service Charge	Nos	15000
103	Bumper Bracket with Labour/Service Charge	Nos	800
104	Bumper Trim with Labour/Service Charge	Nos	200
105	Central Locking System with Labour/Service Charge	set	6800
106	Door Components with Labour/Service Charge	set	200
107	Door Handel Trim with Labour/Service Charge	set	700
108	Engine Cover with Labour/Service Charge	Nos	3000

SL	Description of Item (LOT 5 Toyota Prado/Fortuner)	Unit	CHHEME AUTO
109	Fender with Labour/Service Charge	Nos	5000
110	Fender Bracket with Labour/Service Charge	set	100
111	Fender Trim with Labour/Service Charge	set	200
112	Fog Lamp Cover with Labour/Service Charge	Nos	1800
113	Foot Step with Labour/Service Charge	Nos	7800
114	Front Grill with Labour/Service Charge	set	9999
115	Frot Grill Trim with Labour/Service Charge	set	200
116	Indicator with Labour/Service Charge	Nos	10
117	Interior Mirror with Labour/Service Charge	Nos	500
118	Tailgate Surt with Labour/Service Charge	Nos	200
119	Accelerator Cable with Labour/Service Charge	Nos	500
120	Bonnet Release Cable with Labour/Service Charge	Nos	2200
121	Brake Cable with Labour/Service Charge	set	500
122	Clutch Cable with Labour/Service Charge	set	300
123	Door Lock Link with Labour/Service Charge	set	300
124	Fuel Lid Cable with Labour/Service Charge	Nos	1500
125	Gear Shift Cable with Labour/Service Charge	Nos	300
126	Seat Cable with Labour/Service Charge	Nos	500
127	Temperature Control Cable with Labour/Service Charge	Nos	800
128	Antenna Cable with Labour/Service Charge	Nos	300
129	Alternator with Labour/Service Charge	Nos	9000
130	Battery with Labour/Service Charge	Nos	8200
131	Battery Terminal with Labour/Service Charge	pair	200
132	Battery Terminal Cap with Labour/Service Charge	pair	50
133	Bonnet Release Cable with Labour/Service Charge	Nos	0
134	Boot Release Cable with Labour/Service Charge	Nos	0
135	Fuse with Labour/Service Charge	Nos	100
136	Glow Plug with Labour/Service Charge	Nos	4000
137	Mirror Actuator with Labour/Service Charge	Nos	900
138	Power Window Motor with Labour/Service Charge	Nos	2000
139	Printed Circuit Board with Labour/Service Charge	Nos	900
140	Radiator Fan Motor with Labour/Service Charge	Nos	2500
141	Reflector with Labour/Service Charge	Nos	600
142	Relay with Labour/Service Charge	Nos	650
143	Sensor with Labour/Service Charge	Nos	500
144	Spark Plug with Labour/Service Charge	set	20

SL	Description of Item (LOT 5 Toyota Prado/Fortuner)	Unit	CHHEME AUTO
145	Speedometer Cable with Labour/Service Charge	Nos	300
146	Starter with Labour/Service Charge	Nos	25000
147	Starter Relay with Labour/Service Charge	Nos	650
148	Voltage Stabilizer with Labour/Service Charge	Nos	400
149	Air Supply with Labour/Service Charge	Nos	100
150	Belt and Chain Drive with Labour/Service Charge	set	500
151	Big End Bearing with Labour/Service Charge	set	100
152	Camshaft Bush with Labour/Service Charge	set	400
153	Camshaft Gear with Labour/Service Charge	set	500
154	Camshaft Seal with Labour/Service Charge	Nos	500
155	Carburettor with Labour/Service Charge	Nos	100
156	Connecting Rod with Labour/Service Charge	Nos	2500
157	Control Unit Glow Plug System with Labour/Service Charge	Nos	900
158	Cooler EGR with Labour/Service Charge	Nos	600
159	Cooling System with Labour/Service Charge	Nos	900
160	Crankcase Gasket with Labour/Service Charge	set	100
161	Crankshaft Bearing with Labour/Service Charge	set	1500
162	Crankshaft Gear with Labour/Service Charge	Nos	500
163	Crankshaft Seal with Labour/Service Charge	Nos	900
164	Cylinder Block with Labour/Service Charge	Nos	7000
165	Cylinder Head with Labour/Service Charge	Nos	12000
166	Cylinder Head Cover with Labour/Service Charge	Nos	500
167	Cylinder Head Gasket set with Labour/Service Charge	set	2800
168	Distributor with cap with Labour/Service Charge	Nos	300
169	Distributor Rotor with Labour/Service Charge	Nos	700
170	Drain Plug with Labour/Service Charge	Nos	750
171	EGR Valve and Gasket with Labour/Service Charge	set	300
172	Engine Block with Labour/Service Charge	Nos	0
173	Engine Bracket with Labour/Service Charge	Nos	200
174	Engine Full Gasket Set with Labour/Service Charge	Nos	4500
175	Engine Manifold with Labour/Service Charge	Nos	900
176	Exhaust Manifold Gasket with Labour/Service Charge	Nos	1200
177	Fan Clutch with Labour/Service Charge	Nos	200
178	Flywheel with Labour/Service Charge	Nos	8000
179	Fuel Rail with Labour/Service Charge	Nos	200
180	Heat Shield with Labour/Service Charge	Nos	500

SL	Description of Item (LOT 5 Toyota Prado/Fortuner)	Unit	CHHEME AUTO
181	Idle Control Valve Air Supply with Labour/Service Charge	Nos	300
182	Ignition with Labour/Service Charge	Nos	300
183	Ignition Cable with Labour/Service Charge	set	100
184	Ignition Capacitor with Labour/Service Charge	Nos	200
185	Ignition Coil with Labour/Service Charge	set	200
186	Ignition Module with Labour/Service Charge	Nos	200
187	Ignition Plug Sleeve Connector with Labour/Service Charge	set	200
188	Injector with seal with Labour/Service Charge	set	600
189	Intake Manifold Gasket with Labour/Service Charge	Nos	900
190	Intercooler Mounting Bracket with Labour/Service Charge	Nos	300
191	Oil Cooler Gasket with Labour/Service Charge	Nos	600
192	Oil Dipstick with Funnel with Labour/Service Charge	Nos	1200
193	Oil Filler Cap and Seal with Labour/Service Charge	Nos	200
194	Oil House with Labour/Service Charge	Nos	100
195	Oil pressure Switch with Labour/Service Charge	Nos	300
196	Oil Pump Seal Gasket with Labour/Service Charge	Nos	200
197	Oil Separator with Labour/Service Charge	Nos	500
198	Oil Spray Nozzle with Labour/Service Charge	Nos	200
199	Oil Sump Gasket with Labour/Service Charge	Nos	200
200	O-Ring Set Cylinder with Labour/Service Charge	set	200
201	PCV Breather Hose with Labour/Service Charge	Nos	200
202	PCV Valve with Labour/Service Charge	Nos	200
203	Radiator Cap with Labour/Service Charge	Nos	600
204	Radiator Hose with Labour/Service Charge	Nos	800
205	Starter Motor Assembly with Labour/Service Charge	set	300
206	Throttle Body with Seal with Labour/Service Charge	Nos	3000
207	Timing Case Gasket with Labour/Service Charge	Nos	600
208	Coolant with Labour/Service Charge	L	400
209	Coolant Control Valve with Labour/Service Charge	Nos	300
210	Coolant Flange with Labour/Service Charge	Nos	450
211	Coolant Pipe Seal with Labour/Service Charge	Nos	200
212	Coolant Tank with Labour/Service Charge	Nos	2800
213	Coolant Temperature Sensor with Labour/Service Charge	Nos	500
214	Coolant Fan with Labour/Service Charge	Nos	2000
215	Radiator with Labour/Service Charge	Nos	22000
216	Catalytic Convertor with Labour/Service Charge	Nos	500

SL	Description of Item (LOT 5 Toyota Prado/Fortuner)	Unit	CHHEME AUTO
217	Cooler EGR with Labour/Service Charge	Nos	0
218	Diesel Particulate Filter with Labour/Service Charge	Nos	1500
219	EGR Pipe with Labour/Service Charge	Nos	900
220	Intercooler with Labour/Service Charge	Nos	2000
221	Lambda Sensor with Labour/Service Charge	set	200
222	Resonator with Labour/Service Charge	Nos	300
223	Silencer with Labour/Service Charge	Nos	4500
224	Turbocharger with Gasket with Labour/Service Charge	set	16000
225	Fuel Pump Filter with Labour/Service Charge	Nos	300
226	Fuel Pump Seal with Labour/Service Charge	set	200
227	Fuel Sensor with Labour/Service Charge	Nos	700
228	Fuel System Connector with Labour/Service Charge	Nos	800
229	Fuel Valve with Labour/Service Charge	Nos	200
230	Fuel Filter with Labour/Service Charge	Nos	0
231	Fuel Lid Cable with Labour/Service Charge	Nos	0
232	Fuel Lid Opener Lever with Labour/Service Charge	Nos	800
233	Fuel Pressure Regulator with Labour/Service Charge	Nos	300
234	Fuel Pump with Labour/Service Charge	Nos	800
235	Bonnet Seal with Labour/Service Charge	Nos	200
236	Camshaft Seal with Labour/Service Charge	Nos	500
237	Window Seal with Labour/Service Charge	Nos	300
238	Contact Breaker with Labour/Service Charge	Nos	200
239	Window Regulator with Labour/Service Charge	Nos	5800
240	Air Vent with Labour/Service Charge	Nos	300
241	Armrest with Labour/Service Charge	Nos	500
242	Ashtray with Labour/Service Charge	Nos	200
243	Door Handle with Labour/Service Charge	Nos	2500
244	Door Lock with Labour/Service Charge	set	900
245	Door Lock Knob with Labour/Service Charge	Nos	200
246	Glove Box with Lock and Key with Labour/Service Charge	set	200
247	Headrest with Labour/Service Charge	set	900
248	Interior Door Panel with Labour/Service Charge	Nos	200
249	Interior Grab Handel with Labour/Service Charge	Nos	200
250	Interior Mirror with Labour/Service Charge	Nos	2200
251	Pedal Pad with Labour/Service Charge	Nos	200
252	Sun Visor with Labour/Service Charge	Nos	1900

SL	Description of Item (LOT 5 Toyota Prado/Fortuner)	Unit	CHHEME AUTO
253	Steering Column Switch with Labour/Service Charge	Nos	200
254	Window Crank with Labour/Service Charge	Nos	200
255	Window Regulator Sliding Shoe with Labour/Service Charge	Nos	20
256	Window Switch with Labour/Service Charge	set	3200
257	AC Compressor Oil with Labour/Service Charge	L	400
258	Steering Oil with Labour/Service Charge	L	500
259	Transmission Oil with Labour/Service Charge	L	100
260	Windshield Washer Fluid with Labour/Service Charge	L	200
261	Air Filter Pipe with Labour/Service Charge	Nos	100
262	HAVAC Hose with Labour/Service Charge	Nos	200
263	Radiator Hose with Labour/Service Charge	Nos	600
264	Turbocharger Hose with Labour/Service Charge	Nos	500
265	ABS Sensor with Labour/Service Charge	Nos	5800
266	AC Control Unit with Labour/Service Charge	Nos	700
267	Adjusting Potentiometer with Labour/Service Charge	Nos	200
268	Blower Motor Resistor with Labour/Service Charge	Nos	100
269	Brake Pad Wear Sensor with Labour/Service Charge	Nos	100
270	Centre Rod Assembly with Labour/Service Charge	set	100
271	Horn Pad with Labour/Service Charge	Nos	100
272	Idler Arm with Labour/Service Charge	Nos	200
273	Inner Tie Rod with Labour/Service Charge	Nos	100
274	King Pin with Labour/Service Charge	Nos	200
275	Pitman Arm with Labour/Service Charge	Nos	200
276	Power Steering Motor with Labour/Service Charge	Nos	25000
277	Power Steering Pump with Labour/Service Charge	Nos	1400
278	Power Steering Reservoir with cap with Labour/Service Charge	Nos	2200
279	Steering Angle Sensor with Labour/Service Charge	Nos	500
280	Steering Bracket with Labour/Service Charge	Nos	200
281	Steering Column with Labour/Service Charge	Nos	4500
282	Steering Column Coupler with Labour/Service Charge	Nos	200
283	Steering Column Cover with Labour/Service Charge	Nos	200
284	Steering Column Switch with Labour/Service Charge	Nos	200
285	Steering Damper with Labour/Service Charge	Nos	200
286	Steering Gear Assembly with Labour/Service Charge	set	200
287	Steering Wheel with Labour/Service Charge	Nos	200
288	Tie Rod End with Labour/Service Charge	Nos	3200

SL	Description of Item (LOT 5 Toyota Prado/Fortuner)	Unit	CHHEME AUTO
289	Steering Rack and Boot with Labour/Service Charge	set	55000
290	Arm Bush with Labour/Service Charge	set	1200
291	Beam Axle with Labour/Service Charge	Nos	900
292	Compressed Air System with Labour/Service Charge	Nos	600
293	Inner Tie Rod with Labour/Service Charge	Nos	50
294	Leaf Spring Shackle with Labour/Service Charge	Nos	700
295	Shaft Seal Wheel Hub with Labour/Service Charge	Nos	400
296	Spring with Labour/Service Charge	Nos	6000
297	Suspension Links with Labour/Service Charge	Nos	200
298	Suspension Nut Bolt and Seal with Labour/Service Charge	Nos	200
299	Suspension Bracket with Labour/Service Charge	Nos	200
300	Steering Knuckle with Labour/Service Charge	Nos	22000
301	Tyre Valve with Labour/Service Charge	Nos	100
302	Wheel Cover with Labour/Service Charge	set	500
303	Bolt with Labour/Service Charge	Nos	50
304	Cable Strap with Labour/Service Charge	Nos	100
305	Circlip with Labour/Service Charge	Nos	10
306	Clamp with Labour/Service Charge	Nos	50
307	Clip with Labour/Service Charge	Nos	50
308	Fasteners with Labour/Service Charge	Nos	200
309	Grease with Labour/Service Charge	Nos	600
310	Grommet with Labour/Service Charge	Nos	200
311	Nut with Labour/Service Charge	Nos	50
312	O-Ring with Labour/Service Charge	Nos	200
313	Plug with Labour/Service Charge	Nos	50
314	Rivet with Labour/Service Charge	Nos	100
315	Screw with Labour/Service Charge	Nos	50
316	Sealing Substance with Labour/Service Charge	Nos	200
317	Spacer with Labour/Service Charge	Nos	300
318	Stud with Labour/Service Charge	Nos	200
319	Tightening Strap with Labour/Service Charge	Nos	100
320	Washer with Labour/Service Charge	Nos	50
321	ABS Ring with Labour/Service Charge	Nos	400
322	Drive Shaft with Labour/Service Charge	Nos	25000
323	Drive Shaft Boot with Labour/Service Charge	Nos	200
324	Propeller Shaft with Labour/Service Charge	Nos	8500

SL	Description of Item (LOT 5 Toyota Prado/Fortuner)	Unit	CHHEME AUTO
325	Rim with Labour/Service Charge	Nos	400
326	Spare Wheel Cover with Labour/Service Charge	Nos	0
327	Wheel Balancing Weight with Labour/Service Charge	Nos	200
328	Wheel Bearing with Labour/Service Charge	Nos	50
329	Wheel Hubs with Labour/Service Charge	Nos	9500
330	Connector Washer Fluid Pipe with Labour/Service Charge	Nos	200
331	Rain Sensor with Labour/Service Charge	Nos	200
332	Washer Fluid Pipe with Labour/Service Charge	Nos	200
333	Windshield Washer Bracket with Labour/Service Charge	Nos	200
334	Windshield Washer Pump with Labour/Service Charge	Nos	400
335	Windshield Washer Jet with Labour/Service Charge	Nos	200
336	Windshield Washer Reservoir with cap with Labour/Service Charge	Nos	200
337	Wiper Arm with cap with Labour/Service Charge	Nos	1800
338	Wiper Blade with Labour/Service Charge	set	1200
339	Wiper Blade Rubber with Labour/Service Charge	set	600
340	Wiper Linkage with Labour/Service Charge	set	900
341	Wiper Motor with Labour/Service Charge	Nos	1500
			<b>692819</b>